Work Orde Vednesday, July										,		Page 1
Revision ID:	D3565-1 Wearplate		A	Accept				S	etup	Start Stop		
	7/14/2010	Start Qty: 4.00 Req'd Qty: 4.00			Cust Ite Custom	[	ı			; ;		9 <u>11 1181 1881</u>
Approvals:	Process Plan	n:/	Date/ <i>D-7-14</i>	Tooling:  SPC (Y/N):		Date:		I		Start Stop		(18 18 18 18 18 18 18 18 18 18 18 18 18 1
Sequence ID/ Work Center ID		Operation Description	· · · · · · · · · · · · · · · · · · ·	Set Up/ Run Hours	Tool I	D Tool#	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
Draw Nbr	Revi	sion Nbr							,		, ,	.:
D3565	Rev	С		·			- Tu-1" - 150 1		····			
Waterjet FLOW CNC Waterje			per Dwg D3565 □Dwg Rev: necessary	0.00 0.00 □Prog Rev:_	□2-			_B	<u> </u>	16-		<i>(8)</i>
	<del>5.</del>	QC2- Inspect parts of	f machine FAI/FAIB	0.00	ì		·	.e.	: - رحی	- > (		<i>•</i>
QC Quality Control		Memo		0.00				<u>- c,y</u>	<u> </u>	(	+ ************************************	<del></del>
	•	QC8- Inspect parts - s	econd check	0.00	)(v4122		!	(Se	;			
QC Quality Control		Memo		0,00				A5	+- د		+**+1	

Dart Aerospac	e Ltd
---------------	-------

		- <del></del>						· ·	
W/O:			WO	RK ORDER CHANG	ES				•
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						,			
Part No	):	PAR #:	Fault Cated	orv:	NCR: Yes	No DQA		Date:	<u> </u>
		esolution:					1		
NCR:	*	,	WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
DATE	OTED	Description of NC	<del></del>	Corrective Action Section		Verifica	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sectio	n C	Chief Eng	QC Inspector
								Ž.	
								*.5	
		<u></u>							
li .									
					-				
								1	

						i						
<b>Work Ordo</b> Wednesday, July								,				Page 2
Item ID: Revision ID:	D3565-1			Accept					Setup	Start Stop		
Item Name: Start Date: Required Date: Reference:	Wearplate 7/14/2010 7/22/2010	Start Qty: 4.00 Req'd Qty: 4.00			Cust Ite Custom		1			i i	1 1881  181 111	<b>iji ili ilbi ibb</b> i
Approvals:		an:	Date:	Tooling: SPC (Y/N):		Date:			Run	Start Stop		
Sequence ID/ Work Center II	)	Operation Description		Set Up/ Run Hours	Tool I	D Tool#	Plan Code	Accep Qty	t Rej Qty		Reject Number	Insp. Stamp
Large Fab		D3565 using	09-3 cups as per dwg D3 g DT8991 jig□A/R 20 1 / / 4 705	0.00 0.00 565□2-Weld hard facing 059B Hard Coat rod	as per Dwg		ì	_E	2	10	-7-2	8 X8
140 QC Quality Control	s.	QC9- Inspect visual per (	QS1004- Fusion Welds	0.00	,		,		_ G		10.0	7.28
,											ş	

150 QC

0.00

85/w/o/28

Quality Control

Memo

QC5- Inspect part completeness to step on W/O

	•	<del></del>									
W/O:	,		WC	RK ORDER CHANGE	ES				1		
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		· 1									
<del></del> ;											
Part No	•	PAR #:	Fault Cated	JOLV.	NCR: Ves	No DOA:		Date:			
		esolution:							_		
NCR:		,	WORK ORD	R NON-CONFORMA	NCE (NCF	R)		Date:			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	Sign 8	Jection	i <b>on</b> C		Approval QC Inspector		
			Chief Eng	Chief Eng	Date						
	-							•:			
	,										
-											

### Work Order ID 60558



Page 3

Wednesday, July 14, 2010 9:17:05 AM

Item ID:

D3565-1

Item Name:

**Revision ID:** 

Wearplate

**Start Date:** 

Required Date: 7/22/2010

7/14/2010

Start Qty: 4.00

Reg'd Oty: 4.00



Accept

Setup Start



Stop

Reference:

Approvals:

Process Plan:

QC:

Date: Tooling:

Date: **SPC (Y/N):**  Date:

Tool # Plan

Code

Date:

Cust Item ID:

**Customer:** 

**Tool ID** 

Run

Accept

Qty

Start



Stop

Reject

Qty

Insp.

Stamp

Sequence ID/ **Work Center ID** 

160

Powdercoat

Powder Coating

Operation Description

Grey Sandtex(Ref:4.3.5.6) per QSI005 4.3

**Run Hours** 

0.00

Set Up/

170

QC

Quality Control

QC3- Inspect Part Finish

Memo

0.00

0.00

180

Packaging

Identify as per dwg & Stock Location: (1977)

0.00

Memo

0.00

Reject

Number

Packaging

W/O-	•		1817	DK ODDED OLIANO				· ,	c
W/O:			VVC	ORK ORDER CHANGI	<b>E5</b>		1	Approval	
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Chief Eng / Prod Mgr	Approval QC Inspector
		-				}			
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQA</b>		Date:	
	R	esolution:	Dispositio	n:	_ QA: N/C C	losed:		Date: _	
NCR:		\	WORK ORD	ER NON-CONFORMA	NCE (NCF	3)			
DATE	STEP	Description of NC		Corrective Action Section		Verifica	tion	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	🙎   Section		Chief Eng	QC Inspector
						ļ			
					i	1			
							1		
							1	·	

#### Work Order ID 60558

Page 4

Wednesday, July 14, 2010 9:17:05 AM

Item ID:

D3565-1

**Revision ID:** 

Item Name: Wearplate

**Start Date:** 

7/14/2010

Required Date: 7/22/2010

Start Qty: 4.00 Req'd Qty: 4.00

Accept

**Cust Item ID:** 

**Customer:** 

Tool ID

Setup Start

Run

Stop



Reference:

**Approvals:** 

Process Plan: QC:

Operation

Description

Date:

Date: Tooling:

SPC (Y/N):

Set Up/

Date:

Date:

Start

Stop

Sequence ID/

**Work Center ID** 

190

Memo

QC21- Final Inspection - Work Order Release

0.00

**Run Hours** 

0.00

Tool # Plan Code Qty

Accept

Reject Qty

Reject Insp. Number Stampi

Quality Control

									· · · · · · · · · · · · · · · · · · ·
W/O:			WO	RK ORDER CHAN	GES				
DATE	STEP	PR	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	:								
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No <b>DQA</b> :		Date:	
	Re	solution:	Disposition	÷	QA: N/C C	losed:		Date: _	
NCR:	j		WORK ORDE	R NON-CONFORM	IANCE (NC	R)			
DATE	STEP	Description of NC			ction B	Verifica		Approval	Approval
	10121	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ıC	Chief Eng	QC Inspector
								. •	
	1		1				1		

### Picklist Print

Wednesday, July 14, 2010 9:17:09 AM

Work Order ID: 60558

Parent Item:

D3565-1

Parent Item Name: Wearplate



**Start Date:** 7/14/2010

Required Date: 7/22/2010

Page 1

Start Qty: 4.00

Required Qty: 4.00

**Comments:** 

IPP Rev : A New Issue 07-01-16 JLM

IPP rev B

revB dwg 07.04.18 ec

IPP Rev:C rev.c as per dwg 08-01-14 DD verified by: IPP Rev: D QC5 added to step 8 08.12.22 KJ Verified by:

Item Name I	Replacement tem ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3009-3  Cup		Manufactured	No			100	Each	329.0000	3	12	2 /	ر د ر ن	'ー27
				Location		Loc	<u>Oty</u>	Loc Code			f		
				WA			329				!		
					42377		329			24		i.	•
M304S16GA		Purchased	No			130	sf	51.5039	0.135	0.568421	1.1		
304/316 Sheet .063							<b>\</b>				1310-	7-21	<del></del>
				Location		Loc	Oty	Loc Code				1	
				MAT		51.5038	9474 .					(8)	
					111323		0		, _				
					114799	51.503	8947 <sup> </sup>			14799			

W/O:			W	ORK ORDER CHANG	ES				ť	
DATE	STEP	PRO	CEDURE CH	ANGE	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								į		
Part No	:	PAR #:	Fault Cat	egory:	NCR:	Yes N	lo <b>DQA</b> :		_ Date: _	
	R	esolution:	Dispositi	on:	QA: N	/C Clos	sed:		Date:	
NCR:		W	ORK ORI	DER NON-CONFORMA	ANCE (	NCR)				
DATE	STEP	Description of NC			ion B	\: 0	Verifica		Approval	Approval
DAIL	JIL.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	C	Chief Eng	QC Inspector
					į					
								1		

DART AEROSPACE LTD	Work Order:	40558
Description: Wearplate (R44)	Part Number:	D3565-1
Inspection Dwg: D3565 Rev: C		Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST


	X	First Article		Prototype	<b>e</b>	
Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension	Tolerance	Dimension	, rosopt	,	Inspection	

Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension	1010141100	Dimension		,	Inspection	
Ø0.879	+0.010/-0.001	, 879	>=		V BO	
0.75	+/-0.030	,749	4		V	
1.00	+/-0.030	1,001	7		V	
2.00	+/-0.030	7.004	8		V	
2.250	+/-0.010	7.747	8		V	
8.120	+/-0.010	661.8	8		V 17"-	
9.62	+/-0.030	9.616	7		V 0" PLUT	02
0.063	+/-0.010	, 06aO	<b>y</b>		V	
					8	
·						
				, <del></del>		
1		1			l	

Measured by:	R	Audited by:	8	Prototype A	N/A			
Date:	16-7-51	Date:	10/07/02		Date:	N	I/A	

Rev	Date	Change	Revised by Approved
Α	09.05.07	New Issue	KJ/EC A

W/O:				V	ORK ORDER CHANG	ES				
DATE STEP			PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									<b>.</b>	
				Pr. = 1-1	· · · · · · · · · · · · · · · · · · ·				],	
Part No:			PAR #:	Fault Ca	tegory:	_ NCR: Yes	NCR: Yes No DQA: Date:			
Resolutio			n:	Disposition:			osed:	Date: _	Date:	
NCR:				WORK OR	DER NON-CONFORMA	NCE (NCR	)			
DATE	STEP		Description of NC Section A		Corrective Action Section B		Verification	1 Approval	Approval	
	SIEP	P		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector	
					i					
					,					
								(		



		<del></del>								
W/O:			WO	RK ORDER CHANG	ES					<b>4</b> 00 <b>1</b>
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						į				
Part No: PAR #:		PAR #:	Fault Category: NC			ICR: Yes No DQA:		: Date:		
		Disposition: QA								
NCR:			WORK ORDE	R NON-CONFORMA	ANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Section B		on B	Sign &	Verificat		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Date	Section		Chief Eng	QC Inspector
					٠,	_				
						***************************************			e	
						•				
		,								
	1									